

Cherry Lake Reserve



- A Main Soccer Pitches**  
 A1 Undertake works to improve the condition of the turf playing surface.  
 A2 Install bench for spectator seating along fence.  
 A3 Remove the the existing player shelters, and install two-way shelters between the main pitch and the second pitch.  
 A4 Install flexible netting barriers between the pitches to create four goal practice training areas.  
 A5 Replace the existing perimeter fence around both pitches with a new 1.1m high chain-mesh fence.  
 A6 Install a 2.5m high chain-mesh fence behind each of the goals on the main pitch and the second pitch.  
 A7 New chain-mesh compound for storing soccer goals.
- B Third Soccer Pitch**  
 B1 Undertake works to improve the condition of the turf playing surface.  
 B2 Install floodlights along the northern boundary.  
 B3 Install bench seating for players and coaches  
 B4 New secure store room (approximately 20sqm) with 3m verandahs on the western, southern and eastern sides for spectator shelter.
- Four floodlights being installed in 2013  
 Future new floodlights

- C SG McIntosh Pavilion**  
 C1 Demolish the existing pavilion and remove the storage container, and construct a new pavilion (see concept floor plan).  
 C2 Covered spectator area.  
 C3 Retain existing mound for spectator viewing.
- D Other Upgrades**  
 D1 Replace the existing chain-mesh northern boundary fence and remove trees and shrubs in senescence and strengthen the boundary planting.  
 D2 Reinstall gravel surface to grass.  
 D3 Upgrade as an informal warm-up / meeting place for teams, by improving the drainage and re-turfing.  
 D4 Decommission the water storage tank in light of the pavilion redevelopment and the incorporation of environmentally sustainable design features.  
 D5 Install an unsealed path network to improve linkages.  
 D6 Install a pedestrian gate.  
 D7 Install a sealed path network form the sealed carparking and around the pavilion.  
 D8 Replace damaged sections of the southern and eastern boundary fence.
- E Traffic Management**  
 E1 Install a median break to improve traffic flow into and out of the north carriageway of Millers Road.  
 E2 Retain the existing reserve entry.  
 E3 Club member car park (26 sealed, 18 unsealed).  
 E4 Four bay parking drop-off zone.  
 E5 New cross-over for car park exit, left hand turn only.  
 E6 Sealed roadway, unsealed car parking (25 spaces) and sealed and signed accessible carparks (3 spaces).  
 E7 Sealed roadway, unsealed car parking (90 spaces).  
 E8 Improve drainage and stabilise roadway to third pitch, unsealed car parking (46 spaces).  
 E9 Unsealed car parking (66 spaces).  
 E10 Gated access points, used by authorised vehicles only.

