



- 11 Instigate a tree planting program to increase numbers of indigenous trees and to increase natural shade within the Sports Precinct, while maintaining important view lines.
- 18 Provide street lighting along Bluegum Drive to improve safety for road users and pedestrians.
- 19 Reconfigure the intersection to form a T-intersection to assist in defining traffic movements and consider re-orienting main entry.
- 20 Upgrade the tennis pavilion and resurface courts where appropriate. Explore area west of western most tennis court (between dog obedience pavilion) for local scale, temporary spectator seating. Progressively install floodlighting to all tennis courts as deemed necessary to support demand.
- 21 Explore reconfiguring the parking in the laneway adjacent to the Bowls Club with the view of providing additional parking. Provide for safe pedestrian access along Fresno Street to Cherry Lake.
- 22 Any refurbishment of the facility is the responsibility of the Scouts.
- 23 Provide general public seating appropriately located around the Dog Obedience area.
- 24 Continue the upgrade of public toilet facilities. The toilets service an important hub of activity consisting of the Fresno Street BBQ/picnic area, the Cherry Lake Reserve and the Sensory Gardens. Install signage regarding the appropriate use of motorised model boats.
- 25 Construct a shelter over the outdoor stage to service the nearby barbeque facilities as a multi purpose area. Develop the Fresno Street barbeque / picnic area so as to maintain its local use character.
- 43 Provide distance markers to the existing circuit path to Cherry Lake. Provide interpretive signage on wildlife, vegetation and history. Discuss with Melbourne Water the modification of planting where it encroaches on the path, particularly along northern shoreline. Provide linkages to the Kororoit Creek Trail, the proposed wetlands at the western inlet to Cherry Lake and the proposed viewing platform.
- 45 Seek to increase car parking at the Cherry Lake end of Fresno Street.
- 46 Add security lighting where appropriate throughout the precinct.
- 47 Address fencing where appropriate throughout the precinct, including replacement of low timber barriers with higher metal rail and timber post barriers (to match existing within the precinct).

